	*	
9	Approved For Release 2002/06/24 : CIA-RDP75B00326R000200100025-6	COBA
y	OBJX	XEBO1
		e dad
REPLY TO	3 June 1963	*
ATTN OF:	P. E.	
Subject:	Monthly Activities Report for May 1963	;
TO:	Commender WRSP-IV	
	1. Flight Activities: A total of twenty-five (25) high flights were supported by the personal equipment section during this reporting period.	
. *	There were no personal equipment discrepancies reported.	
STATINTL	2. Training: Operations Officer for Detachment "H" was checked out on the personal equipment operations and indoctrinated	
Y 174	in flight training. Pere fitted in partial pressure suits for migh actitude ranges. Initial training has	STATINTL
STATINTL	been started for	STATINTL
CTATINITI		STATINTL
STATINTL STATINTL	returned from on 1 May 1963.	18
STATINTL	4. Leaves took leave from 27 May to 31 May 1963.	\$
STATINTL	5. Seat Pack Maintenance: In addition to routine seat pack maintenance, serviced two (2) LAC seat packs.	
STATINTL	6. Equipment and Material: Five (5) new Q336 faceplates were received 28 May 1963 Which has eased the faceplate shortage. A new partial pressure suit has been received for and fitting will be accomplished ASAP. A modified suit has been received for driver #45 and has been worn for the first time this month. Comments appear favorable but final accept- ance will be determined after minor adjustments and comfort obtained over a long flight. A second suit for driver #55 has been returned to the	
	factory for alterations and modifications.	9
	7. Staging activity and Comments:	
	a. Flights totaled fifteen (15) with no personal equipment discrepancies.	STATINTL
al ·	b. To eliminate the requirement for borrowing oxygen at ferry stops, it is recommended that we carry a smaller 295 or 312 cube inch bottle within P.E. boxes. The volume is adequate to pre-breath four (4) pilots and enable us to set up equipment immediately. Action is being taken to determine availability of this item and it could be serviced from the serviced of the could be serviced from the cou	

Approved For Release 2902/06/24 : CIA-RDP75B00326R000200100025-6 From Personal Equipment standpoint, when conditions permit on operations, it is recommended to fly low since it eliminates STATINTL loading the equipment box aboard support sircraft at last minute. STATINTL d. It is possible to have a transportation problem for P.K. during operation when there is only one vehicle to support operations Should there be a two (2) aircraft operation, P.E. would need a vehicle at least four (4) hours prior to take off full-time. This is primarily for timing and loading factors. STATINTL staging area the only problem was the pilot air conditioning while in the cockpit and transfer. Future stagings to warm areas should include an air conditioning unit for this purpose. In addition, the two air conditioning units recently purchased are in our storage. Air conditioners and dehumitifies will be on future stagings to like areas to provide adequate humidity and temperature control for equipment as well as the pilot. STATINTL Personal Equipment NCOIC